

Technical Data Information Report

RID Number	Transmitter	Transmitter Organization	Receiver	Receiver Organization	Keyword 1
7724.03	Gilmore	Nye County	Darrell Lacy	Nye County NWRPO	Audit
Document Date	4/29/2008	General Document Type	QA Program Doc	Keyword 2	Report
Entry Date	2/19/2010	Detail Document Type	Audit Report	Keyword 3	Response
Document Title/Subject	Receipt of Quality Assurance Audit Report # NWRPO-2008-01 Reponse				
Data Originator/Preparer	Kathy Gilmore				
Data Description	Receipt of response to audit findings and observations (corrective actions being taken), and need for a follow-up surveillance to verify that all deficiencies have been corrected.				
Data Collection Method					
Data Collection Location					
Data Collection Period	3/17-19/2008				
Data Sources	Supporting Documents: Audit Plan (RID 7724); Response to Audit Report (RID 7724.02); Follow-up Surveillance Report (RID 7724.04); Surveillance Plan for Audit (RID 7724.05).				
Data Censoring					
Data Processing					
Data Limitations					
Governing QA Docs:	QAP-18.1 Rev 1				
Frequency of Transmittal	As Required				
Direct Questions About Data To:	NWRPO QA Records Center				